

BG Exploration and Production India Ltd.

FIELDS	WORK DESCRIPTION	YEAR
TAPTI	MTA Riser Guard Clamp installation	24 TH MAY 2009
PANNA	PRE-ENGINEERING Survey	20 TH MAR 2009
TAPTI	Diving Services for Installation MTA Riser GUARD Clamp.	2 ND JULY 2008
PANNA	clam on project installation AT PB & PF Platforms	3 RD MAY 2008
TAPTI	Inspection of Riser Guard, Barge bumper	2 ND APR 2008
PANNA	Installation of Conductor Clamp on Platform PB & PF	2 ND MAY 2008
	Jacket face survey for Conductor Clamp-on Installation on Platform PB & PF	15 TH MAR 2008
TAPTI	Removal of Fishing nets and Inspection of 36" and 42" Tapti Tie-in to South Basin Hazira Trunk Line, Installation of Riser Protector Guard	20 TH FEB 2007
	Providing Diving Supervisor as HSSE Rep. for Riser Installation Project	Dec-2006, Jan 2007
PANNA	Inspection of M. V. Mighty Tide, Annual Inspection of SPM, PLEM, C.P readings- Buoy Hull, Anchor Chains, Sub-sea Hose String, Hull Cathodic Protection, Mooring Chains – measurement of chain angle.	6 th Dec 2006
TAPTI	Support Services Installation of Riser and Installation of Jacket Strengthening Clamps	6 th May 2006
PANNA	Installation of Clamp on crack of 18" spool at PLEM at SPM	March 2006
TAPTI	Well Head Cap Placement works for Rig ENSCO 53	6 th Feb 2006
TAPTI	Riser Inspection Job, 06 Risers at TPP, STA, STC & MTA Platforms.	Apr 2006
TAPTI	Scour Survey and Correction works of Rig ENSCO 53	6 th Jan
	Diving Services for inspection and assessment of Leakage of Pipeline near PLEM location.	5 th Oct
	Support Services for SPM / Tanker Operation and Maintenance, for the year 2005-2006.	March 2007
PANNA	Annual Inspection of PANNA SPM, PLEM, C.P reading Buoy Hull, Anchor Chains, Sub-sea Hose String, Hull Cathodic Protection, Mooring Chains –measurement of chain angle	NOV 2005
PANNA	Double Banking works for Oil tankers at Panna SPM for BG Exploration and Production India Ltd.	May 2005
	Inspection of Barge Bumpers at PD and PE Platforms for assessment of damage	3 rd APR
PANNA	Annual Inspection of SPM, PLEM, C.P readings- Buoy Hull, Anchor Chains, Sub-sea Hose String, Hull Cathodic Protection, Mooring Chains –measurement of chain angle	3 RD MAY
PANNA	Thickness Survey of 10 RISERS at PA Platform - 06 Risers, PB, PD, PE & Mukta Platforms – 04 nos. Decoking and cutting window in P.E. Sump Caisson, Tapti Underwater	3 RD OCT
TAPTI		4 TH JAN

	repair jobs, Securing of barge bumper chains, Checking of FREESPAN CORRECTION ON THE PIPELINE,	
PANNA	Additional Work of Installation of 21 Anodes for SPM at Panna Field	3 RD MAR
	Pre engineering survey of Riser STA, STC, MTA.	3 rd Jan
TAPTI	Replacement of corroded/damaged piggy clamp 10 nos. on Riser MTA, 06 nos. on Riser STC and 0 nos. on Riser STA. Installation of continuity cable for C.P. improvement on all three Riser Piggy back clamp line. Installation of 1000 kg riser clamps on bottom most location on Riser STC. Installation of 750 kg anode clamp on MB16 and injection grouting inside the member. Scour reading of all six leg and Post C.P. reading of all installed clamp. Installation of barge bumper securing chains and C.P. improvement. Above job carried out in TAPTI field in almost nil visibility water and peak current was 7 knots.	May 2003