FIELDS	WORK DESCRIPTION	YEAR
O.N.G.C.L		
K. G. BASIN	Diving Services	7 <sup>Th</sup> OCT 2009
	Installation of Corrosion Cap at well GS-15-AO	16 <sup>Th</sup> MAR 2009
	Installation of Corrosion Cap at well GS-15-AO.	30 <sup>TH</sup> AUG 2008
K. G. BASIN	Diving Services	20 <sup>TH</sup> MAY 2008
	Score survey and rectification of Abann II	APR 2008
K. G. BASIN	Sea Bed Survey, Well Head Capping, Scour Survey and Correction for Rig ABAN II – Diving Services	14 <sup>TH</sup> SEP 2008
K. G. BASIN	Sea Bed Survey, Well Head Capping, Scour Survey and Correction for Rig ABAN II – Diving Services	FEB 2006
	Diving Services for Offshore Drilling Rigs	6 <sup>TH</sup> DEC 2005
	Recovery of SPM Hose	4 <sup>™</sup> JUN 2004
	Deployment of Diving team for assessment of Diving systems onboard Sagar Bhushan.	1 <sup>ST</sup> JULY