

Orient Express Ship Management Ltd

FIELDS	WORK DESCRIPTION	YEAR
	Under-Water Survey of Vessel M.V. Orient and applying Epoxy in crack areas	1st Aug 2008